

11th of June 2019

TX6363, TX6373 and TX6383 Mixing ANZEx and AUSEx Certificates Advisory

This advisory is applicable to the Trolex Gas Detector, TX6363, TX6373 and TX6383, distributed by Austdac Pty Ltd.


The following Trolex Gas Detectors have been sold with the following certificate of conformities;

Gas Detector	AUSEx	ANZEx
TX6363	AUS Ex 03.3879X	ANZEx 12.3015X
TX6373	AUS Ex 02.3862X	ANZEx 12.3016X
TX6383	AUS Ex 02.3842X	ANZEx 12.3021X

Note: All new units sold are under the ANZEx scheme.

The TX6363, TX6373 or TX6383 are sold as a transmitter with a sensor head. The transmitter and the sensor head certificates matched each other when the Gas Detector was originally supplied.

Austdac has found a number of customers have been mixing the transmitter and the sensor head which can lead to a mismatch in the certificates as shown below;





While it is understood that these parts with different certificates could be interchanged and still function even with different certificates, Austdac has queried this with the NSW and Queensland Mines Inspectorate who both state that the certificates must match on the equipment.

Austdac is therefore obliged to correct this by matching up the certificates.

If you have any questions regarding this please contact either Mark Goldsworthy;

Email markg@austdac.com.au or

Telephone 02 8851 5036 or 0409 440 404

or myself, Peter Chan;

Email peterc@austdac.com.au or

Telephone 02 8851 5072 or 0448 939 809

Regards

A handwritten signature in black ink, appearing to be "Peter Chan". The signature is written in a cursive style with a long horizontal stroke at the end.

Peter Chan
Engineering Manager